

Property report 2019

- School house roof Sprayed and treated for moss
- School house roof cleaned and repaired prep for painting
- School house roof painted
- Cleaned out gutters on school grounds
- Remove low branches over fence
- Remove and replace broken fence
- Remove rust and painted fittings on pool
- Carried out school house inspections

Nathn Trethowen